



ADaPT Engineering, Inc.

ADaPT Engineering, Inc.  
800 Maynard Ave. South  
Suite 403  
Seattle, WA 98134  
PH: 206-654-7045  
Fax: 206-654-7048

January 25, 1999

Mr. Jon Julnes  
TILCO Vanguard, Inc.  
20628 Broadway Avenue.  
Snohomish, Washington 98296

Re: Detectable Warnings  
Q-Lube Bonney Lake, Washington

Dear Mr. Julnes:

This is a response to your letter of January 4, 1999 requesting comments on the truncated domes installed by Tilco for the Q Lube in Bonney Lake, Washington. The domes were placed in June 1999 to comply with a city safety issue.

Your product has held up very well in the past six months. When I was on site recently, all domes were intact and there was no sign of the color fading. Your product still looks like in was installed yesterday.

I have investigated the iongevity of your product by touring adjacent sites with Tilco Truncated domes. Your product has held up for the past two years on the two commercial sites visited.

I hope the above provided the information you were seeking. Good luck on your expanded operations. Please feel free to use me as a reference at any time.

Sincerely,

Robert Pottorff

COPY